


























System Softkeys

The following list of softkeys will help you identify them as they appear in the software:

	Abort		Single Feature Mode		Insert Software Card		Enter Time
	Done		Relationship Mode				Enter Date
	Cycle Option		Clear Last Hit		Frown Face Error		Serial Out
	Next Result Window		Print		ISO Tolerance		Scroll Up 10
	Tolerance		Scroll Up		Change Axis		Scroll Down 10
	Lower Menu		Scroll Down		Zero X Axis		Enter Text
	Upper Menu		Next Screen, Move right		Zero Y Axis		Zero XYZ
	Enter Value		Move Left		Zero Z Axis		X Axis
	Change Feature		Probes		Scale Up		Y Axis
	Set Level		Recall Datum		Scale Down		Z Axis
	Set Axis		System Options		Service Utilities		Playback Stop
	Set Origin		Minus 1		Requalify		Store Feature
	Delete Current Block		Plus 1		Qualify Additional Tip		Set Zero
	Incremental Zero		Absolute Zero		Select		Recall Probe Tip
	Tools Menu				Change Sign		

System Softkeys

The following list of softkeys will help you identify them as they appear in the software:

	Counter / Scribe Mode		Projection Point		Part Drawing		Force Cone
	Dial Indicator Mode		Construct From Datum		Print Top View (XY)		Inside Cone
	Height Gauge Mode		Reset Measurement Mode		Print Front View (ZX)		Outside Cone
	Digitize Mode		Playback Utilities		Print Side View (YZ)		Inside Sphere
	Measurements Mode		Execute A Block		Select Probe Type		Outside Sphere
	Datum Menu		Exit Playback		Save Startup Probe		Force Cylinder
	Translate Datum		Statistical Histogram		Delete Program		Outside Cylinder
	Rotate Datum		Enable Statistics		Format Storage Card		Inside Cylinder / Circle
	Constructions		Disable Statistics		List Programs		Outside Circle
	Construct a Line		Delete Record		Save Probe Tip		Force Plane
	Construct a Circle		Statistical Summary		Save Program		Force Line
	Construct a Plane		Statistical Run Chart		Recall Program		X Axis
	Symmetry Line		Copy Mean		Save Datum		Y Axis
	Symmetry Point		Print Headers		Digitize Outline		Z Axis
	SymmetryPlane		Select Reference Feature		Restart Playback		